

Settings with 6 prongs

for soldering K with closed back B and open back L

for sew-on AK with open back L and 4 holes

also available with loop for button (asola)



for Swaro
1012/1028

K 25/1
SS 29/30



K + AK 25/2
SS 34



K + AK 25/3
SS 39



for Swaro
4730

K 25/4
6mm



K + AK 25/5
8mm



K + AK 25/6
10mm



K + AK 25/7
12mm



Settings with 6 prongs

for soldering K with closed back B and open back L

for sew-on AK with open back L and 4 holes

also available with loop for button (asola)



for Swaro
1012/1028

K 25/1
SS 29/30



K + AK 25/2
SS 34



K + AK 25/3
SS 39



for Swaro
4730

K 25/4
6mm



K + AK 25/5
8mm



K + AK 25/6
10mm



K + AK 25/7
12mm



KESSEL — SETTINGS

K 24 / 1 B + L + AK 24 / 1 B



for SWARO 4745 10 mm
or SS 33/34 SWARO 1012/1028
attention: not for SWARO 4825

**K 25/1
SS 30**



**K 26/3 B
2x SS 20**



**K 24/2 B
10 mm**



**K 25/3
SS 40**



**K 26/5 B
1x SS 20
2x 5,3 mm**



**K 24/3 B
SS 42/44
Swaro 1012**



**K 25/4
6 mm**



**K 26/7 B
2x SS 12**



**K 25/5
8 mm**



**K 26/8 B
3x SS 12**



**K 25/6
10 mm**



**K 26/9 B
6x SS 12**



**K 25/7
12 mm**



FRENCH SETTINGS and CUPCHAINS with FRENCH SETTINGS other shapes and sizes available

K 40/10 B+L
SS 46- SS48
Swaro 1012/1028



K 43/3 B+L
12x10 mm
Swaro 4100



K 41/2 B+L
13x7,8 mm
Swaro 4300



K 43/6 B+L
18x13 mm
Swaro 4114



K 42/4 B+L
15x7 mm
Swaro 4200



K 44/7 B+L
18x13 mm
Swaro 4610



KBK 40/8/1
pendant with 1 movable ring
SS 38-40
Swaro 1012/1028



KB 25364 - pendant
SS 33-35
SS 46-48
Swaro 1012/1028



KBK 40/8/2
pendant with 2 movable rings
SS 38-40
Swaro 1012/1028



KS 608/1/80 settings per meter, SS 46-48, Swaro 1012/1028

KESSEL - SETTINGS

K 27/1 B
4x2 mm



K 40/1
SS 12



K 40/10
SS 48



+AK 40/10 with 4 holes

K 27/2 B
4x2 mm



K 40/2
SS 15



K 40/12
SS 60



+AK 40/12 with 4 holes

K 27/3 B
5x2 mm



K 40/3
SS 20



K 40/13
16 mm



K 27/4 B
5x2,5 mm



K 40/4
SS 25



K 40/14
18 mm



K 27/6 B
7x3 mm



K 40/5
SS 30



+AK 40/5 with 4 holes

K 27/7 B
10x3 mm



K 40/6
SS 35



K 40/8
SS 40



K 40/9
SS 45



+AK 40/9 with 4 holes

KESSEL - SETTINGS

K 41/2
13x7,8mm



K 43/2
10x8 mm



K 44/1
8x6 mm



K 41/3
15x11 mm



K 43/3
12x10 mm



K 44/3
10x8 mm



K 43/4
14x10 mm



K 44/4
12x10 mm



K 43/6
18x13 mm



K 44/5
14x10 mm



+AK 44/5 with 4 holes

K 42/1
8x4 mm



+AK 43/6 with 4 holes

K 44/7
18x13 mm



+AK 44/7 with 4 holes

K 42/2
10x5 mm



K 43/8
25x18 mm



K 44/9
25x18 mm



K 42/4
15x7 mm




K 44/10
25x20 mm



KESSEL - SETTINGS

m = millgrain surface

p = plain surface

K 86/15 10 MM	 m	K 90/1 5 MM		K 90/11 10 MM	
K 86/16 12 MM	 m	K 90/2 7 MM		K 90/12 10 MM	
K 86/17 14 MM	 m	K 90/3 8 MM		K 90/13 13 MM	
K 86/18 B 10 MM	 m	K 90/4 10 MM		K 90/14 5 MM	
K 90/5 12 MM		K 90/6 14 MM		K 90/15 6 MM	
K 90/7 6,5 MM SS 30		K 90/8 7 MM		K 90/16 8 MM	
K 90/9 8 MM		K 90/10 9 MM		K 90/17 10 MM	
K 90/18 12 MM		K 90/19 14 MM		K 90/20 6 MM	

Crown Settings (for riveting with center hole 3,1 mm)

Sizes referring to diameter between the claws



K 100/1 /B
15 mm round



K 100/1 /ML
15 mm round



K 100/2 /B
18 mm round



K 100/2 /ML
18 mm round



K 100/4 /B
20 mm round



K 100/4 /ML
20 mm round



K 100/5 /B
22 mm round



K 100/5 /ML
22 mm round



K 100/6 /B
24 mm round



K 100/6 /ML
24 mm round



K 100/7 /B
25 mm round



K 100/7 /ML
25 mm round

Crown Settings (for riveting with center hole 3,1 mm)

Sizes referring to diameter between the claws



K 100/23 /B
18x13 mm pearshape



K 100/23 /ML
18x13 mm pearshape



K 100/15 /B
12x10 mm oval



K 100/15 /ML
12x10 mm oval



K 100/11 /B
18x13 mm oval



K 100/11 /ML
18x13 mm oval



K 100/10 /B
25x18 mm oval



K 100/10 /ML
25x18 mm oval



K 100/18 /B
34x26 mm oval



K 100/18 /ML
34x26 mm oval



K 100/19 /B
40x30 mm oval



K 100/19 /ML
40x30 mm oval

Crown Settings

Sizes referring to diameter between the claws

K 90/1 5mm



K 100/5
22mm




K 90/2 7mm



K 90/3 8mm



K 100/6
24mm



K 90/4 10mm



K 100/15
12x10mm



K 90/5 12mm



K 100/11
18x13mm



K 90/6 14mm



K 100/10
25x18mm



K 100/3
20mm



K 100/18
34x26mm



K 100/4
20mm



K 100/19
40x30mm



Crown Settings

Sizes referring to diameter between the claws

K 90/1 5mm



K 100/5
22mm



K 90/2 7mm



K 90/3 8mm



K 100/6
24mm



K 90/4 10mm



K 100/15
12x10mm



K 90/5 12mm



K 100/11
18x13mm



K 90/6 14mm



K 100/10
25x18mm



K 100/3
20mm



K 100/18
34x26mm



K 100/4
20mm



K 100/19
40x30mm



KESSEL - SETTINGS

K 100/1
15 MM



K 100/10
25 X 18 MM



K 100/2
18 MM



K 100/11
18 X 13 MM



K 100/4
20 MM



K 100/18
34 X 26 MM



K 100/5
22 MM



K 100/19
40 X 30 MM



K 100/6
24 MM



K 100/12
8 X 6 MM



K 100/9
18 MM



K 100/15
12 X 10 MM



Crown Settings (for riveting with center hole 3,1 mm)

Sizes referring to diameter between the claws



K 100/1 /B
15 mm round



K 100/1 /ML
15 mm round



K 100/2 /B
18 mm round



K 100/2 /ML
18 mm round



K 100/4 /B
20 mm round



K 100/4 /ML
20 mm round



K 100/5 /B
22 mm round



K 100/5 /ML
22 mm round



K 100/6 /B
24 mm round



K 100/6 /ML
24 mm round



K 100/7 /B
25 mm round



K 100/7 /ML
25 mm round

Crown Settings (for riveting with center hole 3,1 mm)

Sizes referring to diameter between the claws



K 100/23 /B
18x13 mm pearshape



K 100/23 /ML
18x13 mm pearshape



K 100/15 /B
12x10 mm oval



K 100/15 /ML
12x10 mm oval



K 100/11 /B
18x13 mm oval



K 100/11 /ML
18x13 mm oval



K 100/10 /B
25x18 mm oval



K 100/10 /ML
25x18 mm oval



K 100/18 /B
34x26 mm oval



K 100/18 /ML
34x26 mm oval



K 100/19 /B
40x30 mm oval







K 100/19 /ML
40x30 mm oval

KESSEL - SETTINGS

m = millgrain surface

p = plain surface

K 86/15 10 MM		K 90/1 5 MM		K 90/11 10 MM	
K 86/16 12 MM		K 90/2 7 MM		K 90/12 10 MM	
K 86/17 14 MM		K 90/3 8 MM		K 90/13 13 MM	
K 86/18 B 10 MM		K 90/4 10 MM		K 90/14 5 MM	
K 90/5 12 MM		K 90/6 14 MM		K 90/15 6 MM	
K 90/7 6,5 MM SS 30		K 90/8 7 MM		K 90/16 8 MM	
K 90/9 8 MM		K 90/10 9 MM		K 90/17 10 MM	
K 90/18 12 MM		K 90/19 14 MM		K 90/20 6 MM	

KESSEL - SETTINGS

m = millgrain surface

p = plain surface



K 70/77 B
p
3 mm



K 70/41 B
p
5 mm



K 70/68 B
m
6 mm



K 70/29 B
m
8 mm



K 70/34 B
m
9 mm



K 70/40 B
m
10 mm



K 70/30 B
m
12 mm



K 70/60 B
m
12 mm



K 70/31 B
m
13 mm



K 70/61 B
m
15 mm



K 70/32 B
m
16 mm



K 70/33 B
m
18 mm



K 70/39 B
m



K 70/43 B
m



K 70/37 B
m
16x12 mm



K 70/38 B
m w/ring
16x15 mm



K 70/38 B
m no ring
16x15 mm

KESSEL - SETTINGS

m = millgrain surface

p = plain surface



K 70/76 B
m
6x4 mm



K 70/78 B
m
7x5 mm



K 70/50 B
m
8x6 mm



K 70/51 B
m
10x8 mm



K 70/69 B
m
12x10 mm



K 70/35 B
m
14x10 mm



K 70/36 B
m
18x13 mm



K 70/57 B
m
18x13 mm



K 70/82 B
m
24x12 mm



K 70/83 B
m
24x12 mm



K 70/67 B
m
25x18 mm



K 70/80 B
p
34x26 mm



K 70/66 B
m
40x30 mm



K 70/81 B
p
40x30 mm